

型号: YGH 6246说明书

图纸编号: YGH-QM-03-A292

尺寸: 60*73mm


版本号: A-0

材质: 80g书写纸 正反印刷 风琴折

日期: 2025.09.08





Temperature and Humidity Monitor




Model: YCN-H202R

Diagramm



Placement Ways

1. Attach it to any metal surface directly.
2. Hang it up with the coming lanyard.
3. Place it on desktop with the bracket.



Features

1. Display: LCD display, Humidity, Temperature °C/°F
2. Humidity Display Range: 10%~99%
3. Temperature Range: -9.9°C~60.0°C (14.2°F~140°F)
4. Comfort Level: DRY/COMFORT/WET
5. Totally wireless tabletop and magnet mountable design; And you can use a lanyard to hang temperature humidity monitor in the desired place
6. Battery: Holds on a AAA battery to power

Comfort Level

DRY	Humidity is below 29% (<10%, 10-20%, 21-29%)
COMFORT	Humidity is between 30%-69% (30-39%, 40-60%, 61-69%)
WET	Humidity is above 70% (70-79%, 80-89%, 90-99%)

Face Icon Meaning

	Temperature <19°C (Below 66.2°F)	19°C≤Temperature ≤27°C (Between 66.2°F and 80.6°F)	Temperature >27°C (Above 80.6°F)
Humidity <30%	☹️	😊	☹️
30%≤Humidity ≤70%	😊	😊	😊
Humidity >70%	☹️	😊	☹️

Temperature

1. Temperature Range: -9.9°C~60°C (14.2°F~140°F)
2. Temperature Accuracy: ±1°C (0~40°C), ±2°C (40~60°C)
3. Refresh Rate: 10 seconds
4. Temperature Resolution: 0.1°C (0.1°F)
5. If the temperature is lower than -9.9°C, display: -9.9°C; if higher than 60°C, display: 60°C

Humidity

1. Humidity Range: 10%~99% RH
2. Humidity Accuracy: ±3%~5% RH
3. Refresh Rate: 10 seconds
4. Humidity Resolution: 1%
5. If the humidity is below 10%, display: 10%; If above 99%, display: 99%

Battery Tips

When the power is low, the battery icon [🔋] will appear and remind you to replace the new battery.

Battery Replacement

1. Open the battery cover from the Battery buckle.
2. Insert or replace one AAA battery into the battery compartment with correct polarity (+) and (-) as shown.
3. Insert the battery cover.

°C/°F Switch

Press the [°C/°F] button to switch temperature unit to °C/°F.

Warning

1. Please operate this product under the operating instructions. Do not expose the unit to extreme temperatures, direct sunlight, dust, humidity and soon.
2. Do not disassemble the device privately.
3. Please use a AAA battery to supply for this humidity meter. And please take the battery out when not in use.
4. Please prevent the product from falling.
5. This product is non-waterproof, please stay away from any liquid.
6. When the screen display is unclear, please replace the battery.

Mediaonderdelen.nl
Duinkerkenstraat 9 UNIT C
9723 BN Groningen
Nederland
info@yuconn.nl
@yuconnofficial Made in China

